



DECEMBER 1966

SERVICE SHEET

No. 150

A50/65 MODELS - FORK SLIDING TUBE

To improve steering characteristics,
the angle of drilling and reaming of the wheel spindle
holes on both sliding members has been altered.
Part No. 68-5194 replacing Part No. 68-5146 and Part
No. 68-5195 replacing Part No. 68-5147. Both new
members can be identified by the letter 'A' stamped on
the mudguard bracket.

The new parts are only interchangeable in
pairs.